SPOA10 WIDE SUPPLEMENT

SPOA10 Capacity 10,000 lbs.



INSTALLATION INSTRUCTIONS

LP20468

IN20500
Rev. C 06/18/2013

© June 2013 by Vehicle Service Group. All rights reserved. CO8612.6

Use the figures below to substitute for the Figures in your installation manual.



*NOTE: Dimension is from Inside of Baseplate to Inside of Baseplate.

Fig. 1a



Fig. 12

WIDE SPOA10

PARTS SUPPLEMENT

Left Hand Overhead Assembly (Outer).....N493-1
Right Hand Overhead Assembly (Inner).....N494-1
Overhead Stiffener Angle.....N463
Equalizer Cable
Standard Height.....N3129
EH-1 .....N3130
EH-2 .....N3131
Overhead Hose
Standard Height.....N394
EH-1 .....N370
EH-2 .....N3110

Rotary World Headquarters
2700 Lanier Drive
Madison, IN 47250, USA
www.rotarylift.com

North America Contact Information
Tech. Support:
p 800.445.5438
f 800.578.5438
e userlink@rotarylift.com
Sales: p 800.640.5438
f 800.578.5438
e userlink@rotarylift.com

World Wide Contact Information
World Headquarters/USA: 1.812.273.1622
Canada: 1.905.812.9920
European Headquarters/Germany: +49.771.9233.0
United Kingdom: +44.178.747.7711
Australasia: +60.3.7660.0285
Latin America / Caribbean: +54.3488.431.608
Middle East / Northern Africa: +49.771.9233.0

© Vehicle Service Group℠
Printed in U.S.A., All Rights Reserved. Unless otherwise indicated, ROTARY, and all other trademarks are property of Dover Corporation and its affiliates.